



# Lubetech Pty Ltd Oil Analysis Report

PO Box 264, Salisbury, Queensland 4017, Australia  
Phone: +61 7 3274 5297 Fax: +61 7 3274 5232

<b>Client</b>	<b>Filter Technology Australia Pty Ltd / New South Wales</b>		
<b>Contact</b>	Phillip Marheine	<b>Site</b>	Boral Mt Thorley
<b>Address</b>		<b>Unit ID/Name</b>	Truck Hydraulics
<b>Telephone</b>	02 4932 9996	<b>Manufacturer/Model</b>	
<b>Fax</b>	02 4932 9997	<b>Origin</b>	Hydraulic Reservoir
		<b>Fuel/Oil Type</b>	

### Diagnosis:

Oil and wear condition appear satisfactory. Significant improvement in wear metal levels and Particle Count. At 19/15 the Particle Count is at the upper moderate level. Further filtration is recommended. Continue to monitor.



	36807	36716						Indicative Levels	
	27/09/2002	25/09/2002							
	NO	NO							
Condition Tests									
								0.05	
		ND	ND						
								>10%	
		64	66						
		0.85	0.81						
Wear Metals								15	
		1	6					30	
		2	11					20	
		<1	1					25	
		7	50					15	
		1	5					15	
		6	14					15	
		<1	1					15	
		1	1					80	
		459	503						
Cleanliness								18/15	
		19/15	24/21						
		8046	271789						
		2976	100497						
	318	10746							
	Elevated	Very High							
DR Ferrograph								68	
								48	
								1.1	
								30	
	Wear Types								

